



LET'S GO OUTSIDE

**VelopA B.V.**  
Achthovenerweg 21  
2351 AX Leiderdorp  
Postbus 202  
2350 AE Leiderdorp  
tel +31 (0)71 541 03 21  
fax +31 (0)71 589 41 52  
info@velopa.com  
www.velopa.com

## **Velopump Air / Velopump RepAir Replacement rubbers pump head**

The rubbers in the pump head have to be replaced after appr. 1.000 usages.



**Step 1** - Unscrew the two screws of the pump head



**Step 2** - Lift the cap off the pump head.



**Step 3** - Remove the rubbers



**Step 4** - Place new rubbers according to the instruction and re-assemble the pump head.



1\* article number 31083440 Rubber ring for Velopump Air / RepAir